

Restriction List Sinamics GH150 HMI App V2.2.0 (v02.20.03.00)

ID	Restriction Title	Restriction Description	Restriction Workaround	Product
1	No SC500 connection	GH150 HMI App v2.2.0 is only used for local drive monitoring, diagnostics, and operation. The connection to SIDRIVE IQ is not released.	When connection to SIDRIVE IQ is needed, please use Option C68 (SC500).	GH150
2	Basic diagnostics	Only 8 Active alarm messages for each DO can be shown in HMI. And no alarm history.	For advanced diagnostics please use Starter	GH150
3	Local control mode	Local control mode is not allowed to for permanent control.	No	GH150
4	Control Unit (CU) connection	When CU load is above 70% under dual CU topology, the connection between CU (Vector Drive Object) and Web HMI will sporadically lost. Reconnection will be however automatically done.	No	GH150
5	Multiple language Message loading	Multiple Language message refresh delay. No suggest switching language while running motor.	Switch Screens	GH150